LINE DRIVERS THAT USE MINIMAL METAL LAYERS

ABSTRACT OF THE DISCLOSURE

Line drivers that use minimal metal layers. Line driver connections typically need to be made to various other peripheral circuits. Although multiple metal layers could be used to make all the necessary connections, it is desirable to use the fewest metal layers possible. By keeping all y-direction lines on a first layer, and most of the x-direction lines on a second layer, only two metal layers are required. Additionally, an array cut could be used that allows line drivers to reach upper conductive array lines.